

FAST WRAP PRODUCTIONS LLC

STEEL CONDUIT AND PIPE WRAPPING SERVICE

March 2010

Recently a construction project in the San Francisco Bay area was halted due to financial problems. Six months later the work resumed and the new contractor found significant corrosion had taken place in the underground coated steel conduit especially at threaded connections due to many factors including "loose" threaded connections and the underground conduit work was deemed to be unusable. Damage was also noted on the external coating due to incorrect installation protocol.



Much of this could have been avoided using our procedure, triple wrapping with 20 mil tape of the pipe body and molded sleeves over threaded joints ensures a perfect seal.

